





R1.1 on 090413 for EMI





UX30 IO BD R1.1 Change List

- 1. Remove R9901 and change JACK_SW# to J9901.4 for Headset detect error

UX30 IO BD R1.2 Change List

- 1. Change J9803 from 12G183402207 to 12G18340200T for cost down on Page 1
- 2. Change J9901 Pin 4 , 5 connection define on Page 2